

Handling your fresh paint

01 OUTGASSING

Although the clear coat is cured, it will continue to harden for 30-60 days, this is known as the outgassing period.

02 REASSEMBLY

Be careful. During outgassing, tool slippage on reassembly can cause scratches or chips in fresh paint. Do not clamp the painted frame on work stands during rebuild.

03 TRANSPORT

We only recommend transporting your carbon frame or freshly painted bike with a rack that mounts to the wheels or dropouts. All other racks can damage your frame or finish.

04 CUSTOMIZE

During the outgassing period the clear coat needs to breathe. Hold off on using accessories, bags, stickers, or anything that touches your fresh paint job until the outgassing period passes.

Thanks so much for letting us paint your frame. If you need us for more custom paint work or carbon repair, we will be here for you. Please feel free to share your photos with us. We would love to see your bike after it has been built up, or you riding on your new paint work!



www.velontic.com

info@velontic.com